
WLN1 Stop Sale - Quality Assurance Hold for certain used vehicles equipped with Sport Chrono



WLN1 Stop Sale - Quality Assurance Hold for certain used vehicles equipped with Sport Chrono

Vehicle Blocking

DEALERS SHOULD NOT SELL, LEASE, RENT OR LOAN ANY VEHICLES AFFECTED BY THIS ACTION IN DEALER INVENTORY UNTIL FURTHER NOTICE.

Overview

Porsche is currently investigating emissions performance of certain specific Model Year 2012 to 2018 vehicles equipped with Sport Chrono Package.

While this investigation continues and out of abundance of caution, Porsche is requesting that the following vehicles in dealer's inventory be placed on Quality Assurance hold until further notice.

Model Years	Model	Equipment
2012-2016	991 I Carrera 991 I Cabriolet 991 I 4 991 I 4 Cabriolet 991 I S 991 I S Cabriolet 991 I 4S 991 I 4S	Only if equipped with optional Sport Chrono Package
2015-2016	991 I GTS 991 I GTS Cabriolet 991 I 4 GTS 991 I 4 GTS Cabriolet 991 I 4 GTS Targa	All
2015-2016	991 I Targa 4 991 I Targa 4S	Only if equipped with optional Sport Chrono Package
2015-2017	E2 II Cayenne S	Only if equipped with optional Sport Chrono Package
2016-2018	E2 II Cayenne GTS	Only if equipped with optional Sport Chrono Package
2014-2016	Panamera G1 II Turbo Panamera G1 II Turbo Executive	Only if equipped with optional Sport Chrono Package

2014-2016	Panamera G1 II Turbo S Panamera G1 II Turbo S Executive	All
2013-2014	981 Boxster S 981 Cayman S	Only if equipped with optional Sport Chrono Package

Important Note

- Only specific models listed above are currently subject to this quality assurance hold
- Please refer to the attached VIN list for a list of known vehicles in dealer inventory subject to this hold
- All additional used vehicles added to inventory as defined in the model grid above are subject to this hold until further notice

What Dealers Should Do

DEALERS SHOULD NOT SELL, LEASE, RENT OR LOAN ANY VEHICLES IN DEALER INVENTORY SUBJECT TO THIS NOTICE UNTIL FURTHER NOTICE

What Porsche Will Do

Porsche is working to develop an interim solution and will follow up with additional instructions as soon as they are available.

Please inform all necessary dealer staff of this notice as soon as possible.